

- 17516 - 75

1 OF 14





FIG-1

17516 - 75


2 OF 14



17516 - 75

3 OF 14

FIG - 3




002701 " 444463350


450-75

4 OF 14

F-16-4




17516 - 75  
5 OF 14



a

17516 - 75  
6 OF 14


FIG - 6



17516-75  
7 OF 14

SECTION "A-A" 50

F.C - t




50

, 21

17516 - 75  
OF 14

O E E E E E E E E E E

F, G - 8




17516 - 75

9 OF 14

DEFECTIVE "T" JOINTS

F1G-9



17516 - 75  
0 OF 14




FIG - 10

17516 - 75-1  
GPO 2 FEB 1975





FIG. 1)

17516-75-1

12 of 14



**Fig. 12**

17516-75-  
13 OF 14




FIG. 13A




FIG. 13B




FIG. 13C




FIG. 13D




FIG. 14A




FIG. 14B




FIG. 15




FIG. 16




FIG. 17




FIG. 18